

●廃棄物層内温度測定結果

	工事前	工事中	工事中	工事中	工事(中断)中	工事中	工事中	工事中	工事中	工事中	工事中	工事後	工事後	工事後	工事後	工事後	工事後	工事後	工事後	工事後	工事後	工事後	工事後	工事後	工事後	工事後	工事後		
深度	2015/7/21	2015/8/18	2015/9/14	2015/10/15	2015/12/21	2016/3/17	2016/6/17	2016/9/23	2016/12/16	2017/3/17	2017/6/14	2017/12/15	2018/6/1	2018/12/14	2019/6/12	2019/9/9	2019/12/4	2020/3/2	2020/6/10	2020/9/10	2020/12/10	2021/3/2	2021/6/2	2021/9/2	2021/12/8	2022/3/3	2022/6/3	2022/9/2	2022/12/2
0.0m	29.4	29.8	25.2	23.6	17.4	21.9	25.3	33.3	15.6	19.4	27.9	11.8	25.9	12.1	30.9	33.1	12.5	14.4	29.0	28.8	16.6	13.1	28.1	31.4	16.0	11.9	26.9	23.8	8.4
1.0m	29.3	30.0	25.2	23.9	18.6	22.2	25.3	33.3	15.6	19.2	27.9	11.5	25.9	13.1	30.9	33.1	12.4	14.6	27.8	28.7	16.8	13.3	27.4	30.9	16.0	11.9	25.2	26.9	20.4
2.0m	29.3	30.0	25.2	23.9	18.6	22.2	25.3	33.4	15.6	19.2	27.9	11.5	25.6	14.2	30.9	33.1	12.4	15.0	26.5	28.1	17.2	13.5	24.9	30.1	20.6	12.2	24.5	28.7	22.3
3.0m	29.3	29.9	25.2	23.9	18.7	22.2	25.4	33.4	15.6	19.4	28.0	11.5	25.6	15.2	30.9	33.1	12.7	16.0	25.6	27.3	19.1	14.8	23.7	29.9	22.2	12.5	24.3	29.2	22.6
4.0m	29.3	29.9	25.2	23.9	18.8	22.2	25.4	33.3	15.6	20.1	28.0	11.5	25.6	16.2	30.8	33.1	12.7	17.3	23.4	27.3	20.7	15.8	23.4	29.7	24.5	13.1	24.2	29.7	23.2
4.5m	29.3	29.8	25.2	23.9	18.6	22.2	25.4	33.3	15.6	20.1	28.0	11.5	25.6	16.5	30.8	33.1	12.9	18.3	21.9	27.3	20.7	16.2	23.2	29.7	24.7	13.9	24.0	29.7	23.2



