





メタンの経年変化

日時	2017/7/25 晴	2017/8/22 晴	2017/9/21 晴	2017/10/17 曇り	2017/11/17 晴	2017/12/15 曇	2018/1/19 曇	2018/2/16 曇	2018/3/20 曇	2018/4/18 晴	2018/5/15 晴	2018/6/1 晴	2018/7/2 晴	2018/8/3 晴	2018/9/14 曇	2018/10/11 晴	2018/11/8 曇	2018/12/14 曇	2019/1/18 曇	2019/2/15 曇	2019/3/1 晴	2019/4/15 晴	2019/5/15 晴	2019/6/12 晴	2019/9/9 晴	2019/12/4 晴	2020/3/2 曇	2020/6/10 晴	2020/9/10 晴	2020/12/10 晴
ガス抜孔1	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔3	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔4	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔5	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔6	0.00	0.95	0.70	0.45	1.65	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔7	0.00	0.00	0.00	0.25	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔8	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔9	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔10	11.00	0.00	18.00	20.00	24.00	22.00	16.00	10.00	9.00	7.00	0.75	12.00	2.50	0.00	0.00	3.00	15.00	22.00	1.35	0.00	13.00	12.00	9.00	2.51	0.00	10.00	14.00	3.50	9.00	17.00
ガス抜孔11	2.70	0.00	15.00	16.00	18.00	22.00	13.00	12.00	12.00	10.00	0.00	12.00	0.00	0.00	0.00	2.75	0.00	22.00	12.00	0.00	16.00	12.00	11.00	8.00	0.00	12.00	15.00	7.00	7.00	17.00
ガス抜孔12	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔13	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔14	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔15	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利1	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利3	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利4	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利5	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利6	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利7	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
10日間雨量	4.0	82.0	79.5	56.5	4.0	9.5	44.5	23.5	54.5	12.0	97.0	8.5	129.5	26.5	55.0	15.5	3.5	19.5	5.5	13.0			28.0	47.5	45.0	35.5	0.0	57.0	0.0	



硫化水素の経年変化

日時	2017/7/25 晴	2017/8/22 晴	2017/9/21 晴	2017/10/17 曇り	2017/11/17 晴	2017/12/15 曇	2018/1/19 曇	2018/2/16 曇	2018/3/20 曇	2018/4/18 晴	2018/5/15 晴	2018/6/1 晴	2018/7/2 晴	2018/8/3 晴	2018/9/14 曇	2018/10/11 晴	2018/11/8 曇	2018/12/14 曇	2019/1/18 晴	2019/2/15 曇	2019/3/1 晴	2019/4/15 晴	2019/5/15 晴	2019/6/12 晴	2019/9/9 晴	2019/12/4 晴	2020/3/2 曇	2020/6/10 晴	2020/9/10 晴	2020/12/10 晴
ガス抜孔1	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔3	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔4	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔5	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔6	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔7	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔8	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔9	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔10	0.00	0.00	1.10	0.30	0.00	0.80	0.00	1.10	1.30	0.00	0.00	1.40	0.00	0.00	0.00	0.00	5.80	4.70	0.00	0.00	2.70	2.60	4.20	2.50	0.00	1.80	3.00	2.80	0.00	1.80
ガス抜孔11	0.00	0.00	8.80	7.50	4.80	3.80	0.00	0.00	4.80	3.80	0.00	7.50	0.00	0.00	0.00	2.50	0.00	11.20	0.00	0.00	1.90	3.10	13.50	7.80	0.00	4.10	4.40	4.00	0.60	5.30
ガス抜孔12	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔13	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔14	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
ガス抜孔15	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利1	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利2	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利3	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利4	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利5	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利6	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
砂利7	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	
10日間雨量	4.00	82.00	79.50	56.50	4.00	9.50	44.50	23.50	54.50	12.00	97.00	8.50	129.50	26.50	55.00	15.50	3.50	18.50	5.50	13.00				26.00	47.50	45.00	35.50	0.00	57.00	0.00



●廃棄物層内温度測定結果

深度	廃—No.1観測井内温度(°C)								
	2015/7/21	2015/8/18	2015/9/14	2015/10/15	2015/12/21	2016/3/17	2016/6/17	2016/9/23	2016/12/16
	工事前(曇)	工事中	工事中	工事中	工事(中断)中	工事中	工事中	工事中	工事中
外気温	29.4	29.8	25.2	23.6	17.4	21.9	25.3	32.7	15.6
0.0m	29.4	29.8	25.2	23.6	17.4	21.9	25.3	33.3	15.6
1.0m	29.3	30.0	25.2	23.9	18.6	22.2	25.3	33.3	15.6
2.0m	29.3	30.0	25.2	23.9	18.6	22.2	25.3	33.4	15.6
3.0m	29.3	29.9	25.2	23.9	18.7	22.2	25.4	33.4	15.6
4.0m	29.3	29.9	25.2	23.9	18.8	22.2	25.4	33.3	15.6
4.5m	29.3	29.8	25.2	23.9	18.6	22.2	25.4	33.3	15.6

深度	廃—No.1観測井内温度(°C)								
	2017/3/17	2017/6/14	2017/12/15	2018/6/1	2018/12/14	2019/6/12	2019/9/9	2019/12/4	2020/3/2
	工事中	工事中	工事後	工事後	工事後	工事後	工事後	工事後	工事後
外気温	19.4	27.9	11.8	25.9	12.1	31.3	33.1	12.5	14.4
0.0m	19.4	27.9	11.8	25.9	12.1	30.9	33.1	12.5	14.4
1.0m	19.2	27.9	11.5	25.9	13.1	30.9	33.1	12.4	14.6
2.0m	19.2	27.9	11.5	25.6	14.2	30.9	33.1	12.4	15.0
3.0m	19.4	28.0	11.5	25.6	15.2	30.9	33.1	12.7	16.0
4.0m	20.1	28.0	11.5	25.6	16.2	30.8	33.1	12.7	17.3
4.5m	20.1	28.0	11.5	25.6	16.5	30.8	33.1	12.9	18.3

深度	廃—No.1観測井内温度(°C)		
	2020/6/10 11:24	2020/9/10 10:49	2020/12/10 11:45
	工事後	工事後	工事後
外気温	29.7	28.8	16.6
0.0m	29.0	28.8	16.6
1.0m	27.8	28.7	16.8
2.0m	26.5	28.1	17.2
3.0m	25.6	27.3	19.1
4.0m	23.4	27.3	20.7
4.5m	21.9	27.3	20.7